Supplementary Schedules Reserve Management Plan

Reserve Study with On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2017

Attached exhibits consist of component level detail reports. These reports are intended to supplement, but not be a part of the reserve study as of this same date.

Supplementary Schedules

Reserve Management Plan

Table of Contents

Cover	1
Table of Contents	2
Preparer's Report on Supplemental Information	3
Percent Funded - Annual	4
Expenditures by Year	5
Component List - Full Detail	9



Texas Office (214) 810-4941

www.texasreservestudy.com

matt@FAIreserves.com

Preparer's Report on Supplemental Information Reserve Management Plan

Type I Reserve Study With On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2017

Board of Directors Old Mill Village Salt Lake City, Utah

Report on Supplementary Information

The Supplementary Schedules as listed in the table of contents are presented for purposes of additional analysis and are not a required part of the financial projection. Such information is the responsibility of the Old Mill Village's management and was derived from the underlying component list used to prepare the basic reserve study report. The information has been subjected to the inquiry and other procedures applied in the compilation of the basic reserve study report, and we are not aware of any material modifications that should be made thereto.

Facilities Advisors, Inc. Matt Woytek RS, PRA May 4, 2016

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Percent Funded - Annual

100 %

	100 %						
Beginning	Funded	Beginning	Percent			Exp	enditure
Date	Time Value	Balance	Funded	Contribution	Interest	Futu	ure Cost
01/01/2017	\$ 95,576	5 \$ 14,1	15 14.76	% \$ 1	.6,920 \$	157 \$	7,213
01/01/2018	108,903	1 23,9	79 22.01	1	.7,343	249	8,140
01/01/2019	116,493	33,4	30 28.69	1	.7,776	396	2,917
01/01/2020	129,960	48,6	86 37.46	1	.8,221	580	C
01/01/2021	147,092	2 67,4	87 45.88	1	.8,676	654	12,213
01/01/2022	152,480	74,6	04 48.92	1	.9,143	738	11,144
01/01/2023	159,455	83,3	42 52.26	1	.9,622	729	21,396
01/01/2024	156,463	1 82,2	97 52.59	2	20,112	888	4,112
01/01/2025	171,483	1 99,1	85 57.84	2	20,615	888	21,931
01/01/2026	168,996	98,7	58 58.43	2	1,130	573	54,459
01/01/2027	133,500	66,0	03 49.44	2	1,659	748	2,442
01/01/2028	150,837	7 85,9	68 56.99	2	2,200	763	21,944
01/01/2029	149,030	86,9	88 58.36	2	2,755	952	3,735
01/01/2030	166,266	5 106,9	61 64.33	2	3,324	1,086	10,948
01/01/2031	176,972	2 120,4	23 68.04	2	3,907	1,309	2,070
01/01/2032	197,490	143,5	70 72.69	2	4,505	1,538	2,763
01/01/2033	218,266	5 166,8	50 76.44	2	25,117	1,664	14,251
01/01/2034	228,253	3 179,3	82 78.58	2	25,745	1,764	17,349
01/01/2035	235,793	3 189,5	43 80.38	2	16,389	2,036	O
01/01/2036	261,795	5 217,9	68 83.25	2	7,049	2,302	2,342
01/01/2037	286,549	244,9	78 85.49	2	7,725	2,570	3,126
01/01/2038	311,633	3 272,1	47 87.32	2	28,418	773	218,482
01/01/2039	117,132	2 82,8	57 70.73	2	9,129	932	4,781
01/01/2040	137,354	108,1	38 78.72	2	9,857	1,236	O
01/01/2041	163,537	7 139,2	31 85.13	3	30,603	1,526	2,649
01/01/2042	188,227	7 168,7	11 89.63	3	31,368	1,355	51,632
01/01/2043	163,910	149,8	03 91.39	3	32,152	1,583	8,551
01/01/2044	183,743	174,9	88 95.23	3	32,956	1,858	6,738
01/01/2045	206,538	3 203,0	64 98.31	3	3,780	2,024	19,166
01/01/2046	217,794	1 219,7	04 100.87	3	34,625	1,610	80,029

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Expenditures by Year

Date	Description	Code	Service	Est	Future	Salvage	Net
Date	Description	Code	Date	Life	Cost	Value	Expenditure
Year2017							
01/01/2017	Asphalt Path - East	910-000-0020		2:00 \$	5,305.80 \$	0.00 \$	5,305.80
01/01/2017	Mulch - Replenish	920-001-0014	01/01/2012	5:00	1,080.00	0.00	1,080.00
01/01/2017	Mulch - Replenish	920-002-0014	01/01/2012	5:00	828.00	0.00	828.00
				\$	7,213.80 \$	0.00 \$	7,213.80
Year2018							
01/01/2018	Asphalt Path - Seal	910-000-0005	01/01/2014	4:00	8,140.69	0.00	8,140.69
				\$	8,140.69 \$	0.00 \$	8,140.69
Year2019							
01/01/2019	Concrete	920-001-0008	01/01/2014	5:00	2,548.29	0.00	2,548.29
01/01/2019	Concrete	920-002-0008	01/01/2014	5:00	369.56	0.00	369.56
				\$	2,917.85 \$	0.00 \$	2,917.85
Year2021							
01/01/2021	Fencing - Chain Link	910-000-0021	01/01/2016	5:00	1,617.09	0.00	1,617.09
01/01/2021	Irrigation Controllers	920-001-0012	01/01/2009	12:00	1,324.58	0.00	1,324.58
01/01/2021	Irrigation Controllers	920-002-0012	01/01/2009	12:00	1,324.58	0.00	1,324.58
01/01/2021	Irrigation Controllers	920-003-0012	01/01/2009	12:00	1,324.58	0.00	1,324.58
01/01/2021	Irrigation Controllers	920-004-0012	01/01/2009	12:00	1,324.58	0.00	1,324.58
01/01/2021	Irrigation Controllers	920-005-0012	01/01/2009	12:00	3,973.73	0.00	3,973.73
01/01/2021	Irrigation Controllers	920-006-0012	01/01/2009	12:00	1,324.58	0.00	1,324.58
				\$	12,213.72 \$	0.00 \$	12,213.72
Year2022							
01/01/2022	Asphalt Path - Seal	910-000-0005	01/01/2018	4:00	8,985.80	0.00	8,985.80
01/01/2022	Mulch - Replenish	920-001-0014	01/01/2017	5:00	1,221.92	0.00	1,221.92
01/01/2022	Mulch - Replenish	920-002-0014	01/01/2017	5:00	936.81	0.00	936.81
				\$	11,144.53 \$	0.00 \$	11,144.53
Year2023							
01/01/2023	5.5' Bench	920-001-0001	01/01/2008	15:00	1,101.71	0.00	1,101.71
01/01/2023	5.5' Bench	920-002-0001	01/01/2008	15:00	3,305.13	0.00	3,305.13
01/01/2023	6.5' Benches	920-001-0002	01/01/2008	15:00	3,479.08	0.00	3,479.08
01/01/2023	6.5' Benches	920-002-0002	01/01/2008	15:00	6,958.16	0.00	6,958.16
01/01/2023	7' Picnic Table	920-001-0003	01/01/2008	15:00	1,449.62	0.00	1,449.62
01/01/2023	7' Picnic Table	920-002-0003	01/01/2008	15:00	4,348.85	0.00	4,348.85
01/01/2023	Barbecue Grill	910-000-0006	01/01/2008	15:00	753.80	0.00	753.80
				\$	21,396.35 \$	0.00 \$	21,396.35
Year2024							
01/01/2024	Concrete	920-001-0008	01/01/2019	5:00	2,883.16	0.00	2,883.16
01/01/2024	Concrete	920-002-0008	01/01/2019	5:00	418.12	0.00	418.12
01/01/2024	Concrete Curbing	920-001-0009	01/01/2014	10:00	436.84	0.00	436.84
	Concrete Curbing	920-002-0009	01/01/2014	10:00	374.44	0.00	374.44

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Expenditures by Year

Date	Description	Code	Service Date	Est Life	Future Cost	Salvage Value	Net Expenditure
				\$	4,112.56 \$	0.00 \$	4,112.56
Year2025							
01/01/2025	Play Structure	910-000-0015	01/01/2008	17:00 \$	21,931.25 \$	0.00 \$	21,931.25
				\$	21,931.25 \$	0.00 \$	21,931.25
Year2026							
01/01/2026	Asphalt Path - Seal	910-000-0005	01/01/2022	4:00	9,918.64	0.00	9,918.64
01/01/2026	Fencing - Chain Link	910-000-0021	01/01/2021	5:00	1,829.58	0.00	1,829.58
01/01/2026	Mailbox Kiosks	910-000-0013	01/01/2006	20:00	37,091.23	0.00	37,091.23
01/01/2026	Swingset	910-000-0018	01/01/2009	17:00	5,619.88	0.00	5,619.88
				\$	54,459.33 \$	0.00 \$	54,459.33
Year2027							
01/01/2027	Mulch - Replenish	920-001-0014	01/01/2022	5:00	1,382.49	0.00	1,382.49
01/01/2027	Mulch - Replenish	920-002-0014	01/01/2022	5:00	1,059.91	0.00	1,059.91
				\$	2,442.40 \$	0.00 \$	2,442.40
Year2028							
01/01/2028	Basketball - Goal/Post	910-000-0007	01/01/2008	20:00	1,508.90	0.00	1,508.90
01/01/2028	Fencing - Vinyl	910-000-0011	01/01/2008	20:00	18,516.17	0.00	18,516.17
01/01/2028	Shade Pavilion - Roof	910-000-0016	01/01/2008	20:00	1,918.93	0.00	1,918.93
				\$	21,944.00 \$	0.00 \$	21,944.00
Year2029							
01/01/2029	Concrete	920-001-0008	01/01/2024	5:00	3,262.03	0.00	3,262.03
01/01/2029	Concrete	920-002-0008	01/01/2024	5:00	473.06	0.00	473.06
				\$	3,735.09 \$	0.00 \$	3,735.09
Year2030							
01/01/2030	Asphalt Path - Seal	910-000-0005	01/01/2026	4:00	10,948.33	0.00	10,948.33
				\$	10,948.33 \$	0.00 \$	10,948.33
Year2031							
01/01/2031	Fencing - Chain Link	910-000-0021	01/01/2026	5:00	2,070.01	0.00	2,070.01
				\$	2,070.01 \$	0.00 \$	2,070.01
Year2032							
01/01/2032	Mulch - Replenish	920-001-0014	01/01/2027	5:00	1,564.16	0.00	1,564.16
01/01/2032	Mulch - Replenish	920-002-0014	01/01/2027	5:00	1,199.19	0.00	1,199.19
				\$	2,763.35 \$	0.00 \$	2,763.35
Year2033							
01/01/2033	Irrigation Controllers	920-001-0012	01/01/2021	12:00	1,781.41	0.00	1,781.41
01/01/2033	Irrigation Controllers	920-002-0012	01/01/2021	12:00	1,781.41	0.00	1,781.41
01/01/2033	Irrigation Controllers	920-003-0012	01/01/2021	12:00	1,781.41	0.00	1,781.41
01/01/2033	Irrigation Controllers	920-004-0012	01/01/2021	12:00	1,781.41	0.00	1,781.41
01/01/2033	Irrigation Controllers	920-005-0012	01/01/2021	12:00	5,344.22	0.00	5,344.22

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Expenditures by Year

Date	Description	Code	Service Date	Est Life	Future Cost	Salvage Value	Net Expenditure
01/01/2033	Irrigation Controllers	920-006-0012	01/01/2021	12:00 \$	1,781.41 \$	0.00 \$	1,781.41
				\$	14,251.27 \$	0.00 \$	14,251.27
Year2034							
01/01/2034	Asphalt Path - Seal	910-000-0005	01/01/2030	4:00	12,084.91	0.00	12,084.91
01/01/2034	Concrete	920-001-0008	01/01/2029	5:00	3,690.69	0.00	3,690.69
01/01/2034	Concrete	920-002-0008	01/01/2029	5:00	535.23	0.00	535.23
01/01/2034	Concrete Curbing	920-001-0009	01/01/2024	10:00	559.19	0.00	559.19
01/01/2034	Concrete Curbing	920-002-0009	01/01/2024	10:00	479.31	0.00	479.31
				\$	17,349.33 \$	0.00 \$	17,349.33
Year2036							
01/01/2036	Fencing - Chain Link	910-000-0021	01/01/2031	5:00	2,342.02	0.00	2,342.02
				\$	2,342.02 \$	0.00 \$	2,342.02
Year2037							
01/01/2037	Mulch - Replenish	920-001-0014	01/01/2032	5:00	1,769.71	0.00	1,769.71
01/01/2037	Mulch - Replenish	920-002-0014	01/01/2032	5:00	1,356.77	0.00	1,356.77
				\$	3,126.48 \$	0.00 \$	3,126.48
Year2038							
01/01/2038	5.5' Bench	920-001-0001	01/01/2023	15:00	1,595.60	0.00	1,595.60
01/01/2038	5.5' Bench	920-002-0001	01/01/2023	15:00	4,786.81	0.00	4,786.81
01/01/2038	6.5' Benches	920-001-0002	01/01/2023	15:00	5,038.75	0.00	5,038.75
01/01/2038	6.5' Benches	920-002-0002	01/01/2023	15:00	10,077.49	0.00	10,077.49
01/01/2038	7' Picnic Table	920-001-0003	01/01/2023	15:00	2,099.48	0.00	2,099.48
01/01/2038	7' Picnic Table	920-002-0003	01/01/2023	15:00	6,298.43	0.00	6,298.43
01/01/2038	Asphalt Path	920-001-0019	01/01/2008	30:00	79,315.31	0.00	79,315.31
01/01/2038	Asphalt Path	920-002-0019	01/01/2008	30:00	38,238.70	0.00	38,238.70
01/01/2038	Asphalt Path	920-003-0019	01/01/2008	30:00	56,600.23	0.00	56,600.23
01/01/2038	Asphalt Path - Seal	910-000-0005	01/01/2034	4:00	13,339.47	0.00	13,339.47
01/01/2038	Barbecue Grill	910-000-0006	01/01/2023	15:00	1,091.73	0.00	1,091.73
				\$	218,482.00 \$	0.00 \$	218,482.00
Year2039							
01/01/2039	Concrete	920-001-0008	01/01/2034	5:00	4,175.67	0.00	4,175.67
01/01/2039	Concrete	920-002-0008	01/01/2034	5:00	605.56	0.00	605.56
				\$	4,781.23 \$	0.00 \$	4,781.23
Year2041							
01/01/2041	Fencing - Chain Link	910-000-0021	01/01/2036	5:00	2,649.78	0.00	2,649.78 2,649.78
				Ý	2,043.70 \$	0.00	2,043.76
Year2042 01/01/2042	Asphalt Path - Seal	910-000-0005	01/01/2038	4:00	14,724.28	0.00	14,724.28
01/01/2042	Mulch - Replenish				2,002.26		
01/01/2042	Mulch - Replenish	920-001-0014 920-002-0014	01/01/2037 01/01/2037	5:00 5:00	2,002.26 1,535.07	0.00 0.00	2,002.26 1,535.07
01/01/2042	maion repiction	320 002-0014	01/01/2037	3.00	1,333.07	0.00	1,333.07

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Expenditures by Year

			Service	Est	Future	Salvage	Net
Date	Description	Code	Date	Life	Cost	Value	Expenditure
01/01/2042	Play Structure	910-000-0015	01/01/2025	17:00 \$	33,370.99 \$	0.00 \$	33,370.99
				\$	51,632.60 \$	0.00 \$	51,632.60
Year2043							
01/01/2043	Swingset	910-000-0018	01/01/2026	17:00	8,551.32	0.00	8,551.32
				\$	8,551.32 \$	0.00 \$	8,551.32
Year2044							
01/01/2044	Concrete	920-001-0008	01/01/2039	5:00	4,724.39	0.00	4,724.39
01/01/2044	Concrete	920-002-0008	01/01/2039	5:00	685.14	0.00	685.14
01/01/2044	Concrete Curbing	920-001-0009	01/01/2034	10:00	715.82	0.00	715.82
01/01/2044	Concrete Curbing	920-002-0009	01/01/2034	10:00	613.56	0.00	613.56
				\$	6,738.91 \$	0.00 \$	6,738.91
Year2045							
01/01/2045	Irrigation Controllers	920-001-0012	01/01/2033	12:00	2,395.79	0.00	2,395.79
01/01/2045	Irrigation Controllers	920-002-0012	01/01/2033	12:00	2,395.79	0.00	2,395.79
01/01/2045	Irrigation Controllers	920-003-0012	01/01/2033	12:00	2,395.79	0.00	2,395.79
01/01/2045	Irrigation Controllers	920-004-0012	01/01/2033	12:00	2,395.79	0.00	2,395.79
01/01/2045	Irrigation Controllers	920-005-0012	01/01/2033	12:00	7,187.38	0.00	7,187.38
01/01/2045	Irrigation Controllers	920-006-0012	01/01/2033	12:00	2,395.79	0.00	2,395.79
				\$	19,166.33 \$	0.00 \$	19,166.33
Year2046							
01/01/2046	Asphalt Path - Seal	910-000-0005	01/01/2042	4:00	16,252.85	0.00	16,252.85
01/01/2046	Fencing - Chain Link	910-000-0021	01/01/2041	5:00	2,997.99	0.00	2,997.99
01/01/2046	Mailbox Kiosks	910-000-0013	01/01/2026	20:00	60,778.30	0.00	60,778.30
				\$	80,029.14 \$	0.00 \$	80,029.14

Page 8 of 27

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

5.5' Bench

Item Number	1	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15:00
Category	Grounds	Basis Cost	950.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current		Future
E Perimeter		01/01/2008	01/01/2023	6:00	15:00	1.00 \$	950.00	\$	1,101.71
North Perimet		01/01/2008	01/01/2023	6:00	15:00	3.00 \$	2,850.00	\$	3,305.13
						\$	3,800.00	\$	4,406.84

Comments

Benches appeared in good condition. These are plastic/polymer coated steel benches that will have a typical useful life of approximately 15 years. We recommend replacing all benches at the same time in order to maintain a consistent appearance throughout the property.

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

6.5' Benches

Item Number	2	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15:00
Category	Grounds	Basis Cost	1,000.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fived		

		Service	Replace	Rem	Adj	_	Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future	
Park-Deseret		01/01/2008	01/01/2023	6:00	15:00	3.00 \$	3,000.00 \$	3,479.08	
Park-Country		01/01/2008	01/01/2023	6:00	15:00	6.00 \$	6,000.00 \$	6,958.16	
						\$	9,000.00 \$	10,437.24	

Comments

Benches appeared in good condition. These are plastic/polymer coated steel benches that will have a typical useful life of approximately 15 years. We recommend replacing all benches at the same time in order to maintain a consistent appearance throughout the property.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

7' Picnic Table

Item Number	3	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15:00
Category	Grounds	Basis Cost	1,250.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future	
Park-Deseret		01/01/2008	01/01/2023	6:00	15:00	1.00 \$	1,250.00 \$	1,449.62	
Park-Country		01/01/2008	01/01/2023	6:00	15:00	3.00 \$	3,750.00 \$	4,348.85	
						\$	5,000.00 \$	5,798.47	

Comments

Picnic tables appeared in good condition at time of observation. These are plastic/polymer coated steel picnic tables that will have a typical useful life of approximately 15 years. We recommend replacing all picnic tables at the same time in order to maintain a consistent appearance throughout the property.





Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Asphalt Path

Item Number	19	Measurement Basis	sf
Туре	Common Area	Estimated Useful Life	30:00
Category	Grounds	Basis Cost	2.35
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replace	ement Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Greenbelt		01/01/2008	01/01/2038	21:00	30:00	20095.00 \$	47,223.25	\$ 79,315.31
North Perimet		01/01/2008	01/01/2038	21:00	30:00	9688.00 \$	22,766.80	\$ 38,238.70
East Perimeter		01/01/2008	01/01/2038	21:00	30:00	14340.00 \$	33,699.00	\$ 56,600.23
						\$	103,689.05	\$ 174,154.24

Comments

Similar to asphalt street paving, this path will eventually deteriorate and require replacement. We recommend planning to completely replace the asphalt as opposed to mill and overlay that is typical in streets. Most paths are not thick enough to be milled for resurfacing.





Analysis Date - January 1, 2017

Inflation: 2.50% Investment: 1.00% Contribution Factor: 0.00% Calc: Future

Component List - Full Detail

Asphalt Path - East

Item Number	20	Measurement Basis	sf
Туре	Common Area	Estimated Useful Life	2:00
Category	Grounds	Basis Cost	0.37
Tracking	Logistical	Salvage Value	\$ 0.00
Method	One Time		

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
E Perimeter			01/01/2017	0:00	2:00	14340.00 \$	5,305.80 \$	5,305.80
						\$	5,305.80 \$	5,305.80

Comments

At time of observation, the East perimeter asphalt path appeared in very poor condition and our initial thought was to recommend full replacement. However, at the request of the community manager and according to the association's contractor, the path will undergo major repairs only. This line item is a one-time expense as other line items in this report will include cyclical major maintenance.





Analysis Date - January 1, 2017

Inflation: 2.50% Investment: 1.00% Contribution Factor: 0.00% Calc: Future

Component List - Full Detail

Asphalt Path - Seal

Item Number	5	Measurement Basis	sf
Туре	Common Area	Estimated Useful Life	4:00
Category	Grounds	Basis Cost	0.18
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replaceme	ent Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Community Pa	а	01/01/2014	01/01/2018	1:00	4:00	44123.00 \$	7,942.14 \$	8,140.69
						\$	7,942.14 \$	8,140.69

Comments

This line item is for seal coating and crack filling throughout the community paths. In order to maximize the life of the paths, we recommend reserving to seal coat the entire area every 3 - 4 years. Seal coat will ensure proper levels of emulsion in the asphalt. Crack fill between seal coat cycles on an annual basis using operating funds.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Barbecue Grill

Item Number	6	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15:00
Category	Grounds	Basis Cost	650.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Deseret		01/01/2008	01/01/2023	6:00	15:00	1.00 \$	650.00 \$	753.80
						_	650.00 ¢	752 90

Comments

The estimated useful life of this equipment can vary based on frequency of use, however, the typical useful life of the charcoal grill is approximately 15 years with proper care.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Basketball - Goal/Post

Item Number	7	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	20:00
Category	Grounds	Basis Cost	1,150.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Deseret		01/01/2008	01/01/2028	11:00	20:00	1.00 \$	1,150.00 \$	1,508.90
						\$	1,150.00 \$	1,508.90

Comments

Replace the backboard and goal (rim) on an as needed basis using operating funds. Reserve to replace the support pole every 20 years to maintain appearance and safety.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Concrete

Item Number	8	Measurement Basis	sf
Туре	Common Area	Estimated Useful Life	5:00
Category	Grounds	Basis Cost	1.05
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replace	ement Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Basketball Cou		01/01/2014	01/01/2019	2:00	5:00	2310.00 \$	2,425.50	\$ 2,548.29
Park-Country		01/01/2014	01/01/2019	2:00	5:00	335.00 \$	351.75	\$ 369.56
						\$	2,777.25	\$ 2,917.85

Comments

Due to freeze thaw cycles, snow removal techniques and general wear and tear, we recommend reserving an allowance to replace a percentage of the concrete every 4 -5 years in order to maintain a safe and attractive environment. Completely replacing all concrete in one cycle is unlikely based on current, observed conditions.





Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Concrete Curbing

Item Number	9	Measurement Basis	sf
Туре	Common Area	Estimated Useful Life	10:00
Category	Grounds	Basis Cost	1.05
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace Rem	Adj		Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Deseret		01/01/2014	01/01/2024	7:00	10:00	350.00 \$	367.50 \$	\$ 436.84
Park-Country		01/01/2014	01/01/2024	7:00	10:00	300.00 \$	315.00 \$	\$ 374.44
						\$	682.50 \$	\$ 811.28
Comments								

This reserve allowance is for the curbing at the perimeter of the tot-lot. It is unlikely that the entire area will fail and require replacement at the same time, therefore, we have recommended repair/replacement of approximately 10 % of the area every 10 years.

Analysis Date - January 1, 2017

Inflation: 2.50% Investment: 1.00% Contribution Factor: 0.00% Calc: Future

Component List - Full Detail

Fencing - Chain Link

Item Number	21	Measurement Basis	lf
Туре	Common Area	Estimated Useful Life	5:00
Category	Perimeter Fence	Basis Cost	1.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

				Service	Replace	Rem	Adj	j Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future		
Pond Perimet	e	01/01/2016	01/01/2021	4:00	5:00	1465.00 \$	1,465.00 \$	1,617.09		
						\$	1,465.00 \$	1,617.09		

Comments

Similar to the vinyl rail fence catalogued in this report, the chain link fence was <u>not</u> identified while on site. The community manager furnished photos and a condition statement. The condition of the chain link is currently good. This line item is an allowance to make major repairs every 5 years to ensure proper safety and appearance.



Analysis Date - January 1, 2017

Inflation: 2.50% Investment: 1.00% Contribution Factor: 0.00% Calc: Future

Component List - Full Detail

Fencing - Vinyl

Item Number	11	Measurement Basis	If
Туре	Common Area	Estimated Useful Life	20:00
Category	Perimeter Fence	Basis Cost	28.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service Replace R	Rem	Rem Adj	_	Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Pond Perimete	!	01/01/2008	01/01/2028	11:00	20:00	504.00 \$	14,112.00 \$	18,516.17

Comments

The only fencing included in this line item is at the perimeter of the pond, serving as both decorative and as a safety precaution surrounding the attractive nuisance. At time of observation, this fence was not identified, however, the community manager forwarded photos and spoke to the current condition. The fence appears in good condition.





14,112.00 \$

18,516.17

Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Irrigation Controllers

Item Number	12	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	12:00
Category	Landscaping	Basis Cost	1,200.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Replace Rem	Adj		Replacement Cost	
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
S Greenbelt		01/01/2009	01/01/2021	4:00	12:00	1.00 \$	1,200.00 \$	1,324.58
Along Deseret		01/01/2009	01/01/2021	4:00	12:00	1.00 \$	1,200.00 \$	1,324.58
Park-Deseret		01/01/2009	01/01/2021	4:00	12:00	1.00 \$	1,200.00 \$	1,324.58
Park-Country		01/01/2009	01/01/2021	4:00	12:00	1.00 \$	1,200.00 \$	1,324.58
Along Deseret		01/01/2009	01/01/2021	4:00	12:00	3.00 \$	3,600.00 \$	3,973.73
North Perimet		01/01/2009	01/01/2021	4:00	12:00	1.00 \$	1,200.00 \$	1,324.58
						\$	9,600.00 \$	10,596.63
Comments								

Remaining useful life is based on typical useful life in comparison to equipment age. Expect to replace irrigation controllers every 10 - 12 years under normal conditions and with proper maintenance. It may become necessary for the association to replace these controllers with modern evapotraspiration (ET) based units. ET controllers have a cost of approximately \$3,500/each.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Mailbox Kiosks

Item Number	13	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	20:00
Category	Grounds	Basis Cost	1,650.00
Tracking	Logistical	Salvage Value	\$ 0.00

Method Fixed

		Service	ervice Replace Rem Adj			Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Common Area		01/01/2006	01/01/2026	9:00	20:00	18.00 \$	29,700.00 \$	37,091.23
						\$	29,700.00 \$	37,091.23

Comments

The typical useful life of exterior mail kiosks in this climate is approximately 20 years if properly maintained. The majority of kiosks were manufactured and installed in 2006. Expect to replace kiosks within the next 8 - 9 years.





Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Mulch - Replenish

Item Number	14	Measurement Basis	cuyd
Туре	Common Area	Estimated Useful Life	5:00
Category	Grounds	Basis Cost	18.00
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	Replacement Cost			
Location	Desc.	Date	Date	Life	Life	Quantity	Current		Future
Park-Deseret		01/01/2012	01/01/2017	0:00	5:00	60.00 \$	1,080.00	\$	1,080.00
Park-Country		01/01/2012	01/01/2017	0:00	5:00	46.00 \$	828.00	\$	828.00
						\$	1,908.00	\$	1,908.00

Comments

The tot-lot mulch is extremely low and causing a significant safety concerns. We recommend completely replenishing the mulch this fiscal year. Expect to replace low areas on an annual basis using operating funds while completely replenishing every 5 years. This line item is for complete replenishment.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Play Structure

Item Number	15	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	17:00
Category	Grounds	Basis Cost	18,000.00
Tracking	Logistical	Salvage Value	\$ 0.00

Method Fixed

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Country		01/01/2008	01/01/2025	8:00	17:00	1.00 \$	18,000.00 \$	21,931.25
						\$	18.000.00 \$	21.931.25

Comments

In addition to environmental factors that may lead to deterioration, levels of use also play a major factor in replacement cycles. In this environment, expect the play structure to have a typical useful life of approximately 17 years with proper maintenance and moderate levels of use.





Analysis Date - January 1, 2017

Inflation: 2.50% Investment: 1.00% Contribution Factor: 0.00% Calc: Future

Component List - Full Detail

Shade Pavilion - Roof

Item Number	16	Measurement Basis	SF
Туре	Common Area	Estimated Useful Life	20:00
Category	Grounds	Basis Cost	6.50
Tracking	Logistical	Salvage Value	\$ 0.00
Method	Fixed		

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Country		01/01/2008	01/01/2028	11:00	20:00	225.00 \$	1,462.50 \$	1,918.93
						<u> </u>	1.462.50 \$	1.918.93

Comments

The metal roof on the pavilion is susceptible to hail, ice damage and vandalism. We recommend reserving to replace the shade pavilion roof every 20 years in order to maintain proper appearance and function.



Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

Shade Pavilion - Steel

Item Number	17	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	40:00
Category	Grounds	Basis Cost	6,500.00
Tracking	Logistical	Salvage Value	\$ 0.00

Method Fixed

		Service	Replace	Rem	Adj	_	Replacement Cost		
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future	
Park-Country		01/01/2008	01/01/2048	31:00	40:00	1.00 \$	6,500.00 \$	13,975.04	
						\$	6,500.00 \$	13,975.04	

Comments

The shade pavilion structure is a long-life component. Expect to completely replace the pavilion every 40 years under normal conditions and with proper care.





Analysis Date - January 1, 2017

Inflation:2.50% Investment:1.00% Contribution Factor:0.00% Calc:Future

Component List - Full Detail

41	M	ır	ng	c	ρ	t
•		••	מי	•	·	٠

Item Number	18	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	17:00
Category	Grounds	Basis Cost	4,500.00
Tracking	Logistical	Salvage Value	\$ 0.00

Method Fixed

		Service	Replace	Rem	Adj	_	Replaceme	nt Cost
Location	Desc.	Date	Date	Life	Life	Quantity	Current	Future
Park-Deseret		01/01/2009	01/01/2026	9:00	17:00	1.00 \$	4,500.00 \$	5,619.88
						\$	4.500.00 \$	5.619.88

Comments

Swing sets have a typical useful life of 15 to 17 years when properly maintained. Replacement cost includes removal and replacement labor and materials. The estimated age of this equipment is 8 years, expect to replace within the next 9 years.



